

| | | |
|---|---|--------------------------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | Damage Inventory # 234205 & 234213 | Category E |
| Work Order # 31057 | FIPS # 000-UFAE-02 | Date: 11-27-2017 & 03-13-2018 |
| Site Inspector: Michael Dixon, Jr PE | GPS 18.32920, -64.79213 | |
| Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | |

| | |
|--|-----------------|
| Damage Description: | Photo# 1 |
| Pre-Disaster- Overall West Exterior Wall Elevation | |



| | |
|---|-----------------|
| Damage Description | Photo# 2 |
| West Exterior Wall Elevation (11-27-2017) | |











| | |
|---|-----------------|
| Damage Description: | Photo# 3 |
| D3,D19&D20- West Exterior Wall elevation (06-06-2018) | |



| | |
|--|-----------------|
| Damage Description | Photo# 4 |
| D20,D21&D22- West Exterior Wall Elevation (06-06-2018) | |



| | | | | | |
|---|--|--|--|-------------------|--|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E | |
| Work Order# 31057 FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 | | GPS | |
| Site Inspector: Michael Dixon, Jr PE | | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | | |
| <div> <div>Photo#</div> <div>5</div> </div> <div>D19&D20- North Exterior Wall Elevation (03-13-2018)</div> | | <div> <div>Damage Description</div> <div>Photo#</div> <div>6</div> </div> <div>D4&D6- North Exterior Wall Elevation (03-13-2018) Cropped</div> | | | |
| <div> <div>North Elevation</div> <div> 186°S (T) LAT: 18.329409 LON: -64.792038 ±16.4ft ▲ 103ft </div>  <div>DR 4335/4340 13 Mar 2018, 10:54</div> </div> | | <div>  <div> <div>Damage D4</div> <div>Damage D6</div> </div> </div> | | | |
| <div> <div>Damage Description:</div> <div>Photo#</div> <div>7</div> </div> <div>D3,D19&D23- East Exterior Wall Elevation (11-27-2017)</div> | | <div> <div>Damage Description</div> <div>Photo#</div> <div>8</div> </div> <div>D19&D23- East Exterior Wall Elevation (11-27-2017)</div> | | | |
| <div> <div> SE S SW W NW 150 180 210 240 270 300 </div> <div> 241°SW (T) LAT: 18.329218 LON: -64.791962 ±16.4ft ▲ 67ft </div>  <div> Gutter Missing Your Watermark - See Settings DPNR 27 Nov 2017, 09:11 </div> </div> | | <div> <div>Enighed Est, St John, VI 00830</div> <div> 258°W (T) LAT: 18.329174 LON: -64.791939 ±16.4ft ▲ 58ft </div>  <div> Library back DR-4335/4340 VI DPNR St John 27 Nov 2017, 09:12 </div> </div> | | | |

| | | | | | |
|---|--|---|--|--------------------------------------|--|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E | |
| Work Order # 31057 | | FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 | |
| Site Inspector: Michael Dixon, Jr PE | | GPS | | | |
| | | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | | |
| | | Photo# 9 | | Photo# 10 | |
| D1,D2&D4- South Exterior Wall Elevation (06-06-2018) | | D2,D4&D5- South Exterior Wall Elevation (06-06-2018) | | | |
|  | |  | | | |
| Damage Description: | | Photo# 11 | | Photo# 12 | |
| D4&D19- South Exterior Wall Elevation (07-08-2018) | | D7,D8&D13- West Exterior Window #1 & Door #1 Shutters (11-27-2017) | | | |
|  | |  | | | |

| | | |
|--|---|-------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | Damage Inventory # 234205 & 234213 | Category E |
| Work Order # 31057 FIPS # 000-UFAE-02 | Date: 11-27-2017 & 03-13-2018 | GPS |
| Site Inspector: Michael Dixon, Jr PE | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | |

Damage Description:

Photo# 13

D7- West Exterior Window #1 Shutters (11-27-2017)

Damage Description

Photo# 14

D7- West Exterior Window #2 Shutters (11-27-2017)

Damage Description:

Photo# 15

D7- West Exterior Window #1 & 2 Shutters (11-27-2017)


Damage Description


Photo# 16

D8- West Exterior Door #1 Shutters (11-27-2017)





| | | |
|--|---|-------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | Damage Inventory # 234205 & 234213 | Category E |
| Work Order # 31057 FIPS # 000-UFAE-02 | Date: 11-27-2017 & 03-13-2018 | GPS |
| Site Inspector: Michael Dixon, Jr PE | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | |





| | |
|---|------------------|
| Damage Description: | Photo# 17 |
| D9- West Exterior Door #1 (11-27-2017) | |
|  | |

| | |
|---|------------------|
| Damage Description | Photo# 18 |
| D9- West Exterior Door #1 (06-06-2018) | |
|  | |

| | |
|---|------------------|
| Damage Description: | Photo# 19 |
| D10- East Exterior Door #2 Shutters (11-27-2017) | |
|  | |

| | |
|---|------------------|
| Damage Description | Photo# 20 |
| D10- East Exterior Door #3 Shutters (11-27-2017) | |
|  | |

| | | | | | |
|---|--|---|--|---|--|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E | |
| Work Order# 31057 | | FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 | |
| Site Inspector: Michael Dixon, Jr PE | | GPS | | | |
| Damage Description: | | Photo# 21 | | Damage Description | |
| D11- Lower West Exterior Courtyard Door #4 Shutters (06-06-2018) | | | | D12- South Exterior Window #4,5,&7 Shutters (11-27-2017) | |
|  | | | |  | |
| Damage Description: | | Photo# 23 | | Damage Description | |
| D12- South Exterior Window #8 Shutters (07-08-2018) | | | | D13- South Exterior Window #9 & 10 Shutters (11-27-2017) | |
|  | | | |  | |

| | | | | |
|--|--|---|----|--------------------------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E |
| Work Order # 31057 | | FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 |
| Site Inspector: Michael Dixon, Jr PE | | GPS | | |
| Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | | | |
| Damage Description: | | Photo# | 25 | |
| D13- North Exterior Window #11,12,13,14,15 &16 Shutters (03-13-2018) | | | | |
|  | | | | |
| Damage Description: | | Photo# | 26 | |
| D14- West Exterior Veranda Flag Pole (11-27-2017) | | | | |
|  | | | | |
| Damage Description: | | Photo# | 27 | |
| D15- West Exterior Door Wall Light Sconces Fixtures #1 & 2 (06-06-2018) | | | | |
|  | | | | |
| Damage Description: | | Photo# | 28 | |
| D16- West Exterior Veranda Lamp Post Light Fixture (03-13-2018) | | | | |
|  | | | | |

| | | |
|---|---|--------------------------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | Damage Inventory # 234205 & 234213 | Category E |
| Work Order # 31057 | FIPS # 000-UFAE-02 | Date: 11-27-2017 & 03-13-2018 |
| Site Inspector: Michael Dixon, Jr PE | GPS 18.32920, -64.79213 | |
| Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | |

Damage Description:

Photo# 29

D17.1- West Exterior Door Security Camera #1 Missing (11-27-2017)

Damage Description

Photo# 30

D17.1- West Exterior Door Security Camera #1, Missing (11-27-2017)

Damage Description:





Photo# 31





D17.2- West Exterior Stair Domed Security Camera #2 Existing to Remain (11-27-2017)





Damage Description

Photo# 32

D17.2- West Exterior Ramp Domed Security Camera #3 (11-27-2017)

| | | | | | |
|---|--|---|--|---|--|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E | |
| Work Order# 31057 | | FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 | |
| Site Inspector: Michael Dixon, Jr PE | | GPS | | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | |
| Photo# 33 | | Damage Description | | Photo# 34 | |
| D18- S-East Exterior Air Conditioning Unit #1,2&3 Physical Layout (06-06-2018) | | D18- N-East Exterior Air Conditioning Unit #4 Physical Layout (06-06-2018) | | | |
|  | |  | | | |
| Damage Description: | | Photo# 35 | | Damage Description | |
| D18- S-East Exterior Air Conditioning Manufacturer (06-06-2018) | | | | D18- S-East Exterior Air Conditioning Model Information (06-06-2018) | |
|  | |  | | | |

| | | | | | |
|---|--|---|--|--------------------------------------|--|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E | |
| Work Order # 31057 | | FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 | |
| Site Inspector: Michael Dixon, Jr PE | | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | | |
| | | Photo# 37 | | Photo# 38 | |
| D18- S-East Exterior Air Conditioning Disconnection Switch (06-06-2018) | | D24- Tongue & Grooved Section of Library First Floor Ceiling (SE corner)(11-27-2017) | | | |
|  | |  <p>Enighed Est, St John, VI 00830 180°S (T) LAT: 18.328938 LON: -64.791977 ±98.4ft ▲ 110ft Library roof struck by debris DR-4335/4340 VI DPNR St John 27 Nov 2017, 09:10</p> | | | |
| Damage Description: | | Photo# 39 | | Photo# 40 | |
| D24- Tongue & Grooved Section of Library First Floor Ceiling (SE corner) (11-27-2017) | | D25- Water Leakage and Extensively Discolored Coating Damage of the Basement Masonry Wall (11-27-2017) | | | |
|  | |  <p>Enighed Est, St John, VI 00830 118°SE (T) LAT: 18.329273 LON: -64.791977 ±328.1ft ▲ 169ft Library basement window 2' X 2.6' DR-4335/4340 VI DPNR St John 27 Nov 2017, 09:19</p> | | | |

| | | | | |
|--|--|---|-----------|-------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | | Damage Inventory # 234205 & 234213 | | Category E |
| Work Order # 31057 FIPS # 000-UFAE-02 | | Date: 11-27-2017 & 03-13-2018 GPS | | |
| Site Inspector: Michael Dixon, Jr PE | | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | | |
| Damage Description: | | Photo# | 41 | |
| D25- Water Leakage and Extensively Discolored Coating Damage of the Basement Masonry Wall (11-27-2017) | | | | |
|  | | | | |
| Damage Description: | | Photo# | 42 | |
| D26- West Basement Wall Window Frame and Glass Panes Broken (03-13-2018) | | | | |
|  | | | | |
| Damage Description: | | Photo# | 43 | |
| D27- South Basement Wall Wooden Interior Louvered Window Shutters (03-13-2018) | | | | |
|  | | | | |
| Damage Description: | | Photo# | 44 | |
| D28- South Exterior Wall Window Damaged Window Latch at First Floor (04-10-2018) | | | | |
|  | | | | |

| | | |
|--|---|-------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | Damage Inventory # 234205 & 234213 | Category E |
| Work Order # 31057 FIPS # 000-UFAE-02 | Date: 11-27-2017 & 03-13-2018 | GPS |
| Site Inspector: Michael Dixon, Jr PE | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | |

| | |
|--|------------------|
| Damage Description: | Photo# 45 |
| D29- North Exterior Window #11,12,13,14,15 &16 Shutters (03-13-2018) | |



| | |
|--|------------------|
| Damage Description | Photo# 46 |
| D30- South Exterior Wall Door Broken Glass Panes on the First Floor (06-06-2018) | |




| | |
|---|------------------|
| Damage Description: | Photo# 47 |
| D31- East Exterior Wall Water Damaged Hardwood Flooring at Broken First Floor Window (06-06-2018) | |



| | |
|--|------------------|
| Damage Description | Photo# 48 |
| D32- Contents: Adult Fiction Hardback Novels Water Damaged - 10 shelves that hold approximately 25 books each (11-27-2017) | |



| | | |
|--|---|-------------------|
| Applicant: Dept.of Planning and Natural Resources - STJ | Damage Inventory # 234205 & 234213 | Category E |
| Work Order# 31057 FIPS # 000-UFAE-02 | Date: 11-27-2017 & 03-13-2018 | GPS |
| Site Inspector: Michael Dixon, Jr PE | Damage Facility: JMU4F02 - Bldgs and Equip,Sprauve Library and M | |

| | | | |
|--|------------------|---------------------------|---------------|
| Damage Description: | Photo# 49 | Damage Description | Photo# |
| D32- Contents: Adult Fiction Hardback Novels Water Damaged - 10 shelves that hold approximately 25 books each (11-27-2017) | | | |
|  | | | |

| | | | |
|----------------------------|---------------|---------------------------|---------------|
| Damage Description: | Photo# | Damage Description | Photo# |
| | | | |
| | | | |