PRINCIPAL	MS. EVANS, MS. CHESTERFIELD
ENROLLMENT	438 STUDENTS
SCHOOL OPENED	2000
SITE VISIT DATE	FEB., 2015



NOTE:

- SOME AREAS OF PONDING.
- ISSUES W/ GREASE TRAP, BACKS UP INSIDE OF KITCHEN.
- POSSIBLE SEWER LINE PROBLEM W/ TREE ROOTS.
- WATER IS TRUCKED IN EVERY TWO DAYS TO CISTERNS 1 AND 2.
- PUMP FOR WATER, WATER IS TEST TOO.
- NO FIRE HYDRANTS.
- ENOUGH PARKING FOR TEACHERS AND VISITORS .
- MOST OF STUDENTS BUSED, NO ISSUE W/ PICKUP AND DROP OFF
- HALF OF SCHOOL HAS FENCES
- FENCING AND GATES NEEDED
- RUBBER MATTING NEEDED FOR PLAYGROUND.
- NO ISSUES W/ RAMPS OR SIDEWALK.
- ONLY ONE AREA TO EVACUATE TO.

LEGEND:

FH: FIRE HYDRANT
DI: DRAIN INLET
SMH: SEWER MANHOLE
MH: MANHOLE
GT: GREASE TRAP

ZONE X: AREAS DETERMINED TO BE OUTSIDE THE 0.2% ANNUAL CHANCE FLOODPLAIN

OIA – ASSESSMENT OF BUILDINGS AND CLASSROOMS
US VIRGIN ISLANDS – ST. THOMAS

HHF PLANNERS places for people

Austin Tsutsumi & Associates, Inc. Engineers & Surveyors

YVONNE E. MILLINER-BOWSKY ELEMENTARY SCHOOL

FIGURE 15

DISCLAIMER: SITE PLAN FEATURES ARE CONCEPTUAL AND NOT INTENDED FOR DESIGN PURPOSES