


PRINCIPAL MS. AUDVEY BOWRY
 ENROLLMENT
 SCHOOL OPENED 2000
 SITE VISIT DATE FEB. 2015



NOTE:

- NO FLOODING, SOME LEAKS, POSSIBLY BY OLD CISTERNS
- SEWER IS CONNECTED TO GOV. SYSTEM FOR SEWER, G.I. INSIDE KITCHEN, GETS CLOGGED.
- POTABLE WATER IS CONNECTED TO THE GOV. SYSTEM, NO ISSUES.
- FHs/ RISERS ONSITE, RISERS (4 ONSITE), BEGINNING TO RUST AT THE BOTTOM.
- MOST KIDS WALK, SOME CONGESTION WHEN PICK UP/ DROP OFF/ 1 BUS
- ESL - BUSED TO THIS LOCATION
- NO ISSUES WITH RETAINING WALLS.
- NO ISSUES WITH FENCE
- PLAY FIELD IS ROCKY
- S/W OKAY, EXIT GATES NEED RAMPS FOR WHERE THE GROUND IS LOWER THAN THE SIDEWALK

PLENTY OF TREES
 NEED TO CUT.
 NEEDS REGULAR
 MAINTENANCE

LEGEND:

- MH: MANHOLE
- SMH: SEWER MANHOLE
- DMH: DRAIN MANHOLE
- DI: DRAIN INLET
- FH: FIRE HYDRANT
- GYM: GYMNASIUM
- CONC: CONCRETE

ZONE X: AREAS DETERMINED
 TO BE OUTSIDE THE
 0.2% ANNUAL
 CHANCE FLOODPLAIN

0 50 100 200 300 400 500 FEET



OIA - ASSESSMENT OF BUILDINGS
 AND CLASSROOMS
 US VIRGIN ISLANDS - ST. THOMAS



LOCKHART ELEMENTARY SCHOOL

FIGURE

13

DISCLAIMER: SITE PLAN FEATURES ARE CONCEPTUAL AND NOT INTENDED FOR DESIGN PURPOSES